

NOTICE # FN-PRD-PS-Nplus1-080514-01

Туре	□Product Announcement (PA) ☑Product Support (PS) □End of Life (EoL) □Pricing (PRC) □Sales & Marketing (S&M) □Training (T)
Region Applicable	□APAC □EMEA □NAM ☑AII
Subject	Nplus1 Functionality
Field Notice Date	August 05, 2014
Effective Date	August 05, 2014
Notice Number:	FN-PRD-PS-Nplus1-080514-01

Notice

This field notice is provided on an "as is" basis and does not imply any kind of guarantee or warranty, including the warranty of merchantability. Your use of the information on the field notice or materials linked from the field notice is at your own risk. Meru reserves the right to change or update this field notice at any time.

Summary

Nplus1 slave controller takes over master when master is up.

Description of Field Notice

Nplus1 customers may experience an unexpected failover in their current installations.

Symptoms: As stated, the Nplus1 controller will take over while the master controller is up. This leads to the master controller becoming passive and the slave becoming active, causing a failover.

What to expect:

- At the time of the failover, wireless clients may experience drops/disconnects (usually taking place in under a minute)
- The master will remain online but in a passive state



Cause: Incorrect conversion type from 32 to 64 bit. This can be seen by incorrect timeout value in the np1.log

Immediate Workaround: Special Nplus1 binary should be applied on both master and slave controllers. Two files have to be replaced as part of the solution. Please contact support for applying the patch.

Long term solution: A newer SD release that contains this fix natively will be released in the coming weeks.

Trademarks

Meru and Meru Networks are trademarks or registered trademarks of Meru Networks in the United States. Other company and product names may be trademarks of the respective companies with which they are associated.

Copyright

© 2014 Meru Networks, Inc. All rights reserved.