

## NOTICE # FN-PRD -System Director 5.3-PA -040114-01

Туре	☑Product Announcement (PA)	
	☐Product Support (PS)	
	☐End of Life (EoL)	
	□Pricing (PRC)	
	☐Sales & Marketing (S&M)	
	☐Training (T)	
Region Applicable	□APAC □EMEA □NAM ☑AII	
Subject	Release of System Director 5.3-158	
Field Notice Date	April 1, 2014	
Effective Date	April 1, 2014	
Notice Number:	FN-PRD-System Director 5.3-PA-040114-01	

#### **Notice**

This field notice is provided on an "as is" basis and does not imply any kind of guarantee or warranty, including the warranty of merchantability. Your use of the information on the field notice or materials linked from the field notice is at your own risk. Meru reserves the right to change or update this field notice at any time.

### Summary

General release of System Director 5.3-158

## **Description of Field Notice**

This release of Meru System Director (release 5.3-158) provides fixes that address the critical bugs related to controller and AP issues that were not included in the previous release. There were no new feature enhancements implemented.

Major changes to the v5.3-158 release were associated with:

- 1. Client association reliability with three stream clients
- 2. Client disconnections caused by frequent handoffs triggered by controller
- 3. Several security authentication corner cases
- 4. Fixed memory leak and packet drops on the AP320
- 5. Fixed several controller based problems related to QoS rules, VLAN assignments, and RADIUS

Please refer to the SD-5.3-158 release notes for installation, troubleshooting, and change details



# **Supported/Non-Supported Hardware and Software versions**

Hardware/Software	Supported	Non-Supported
Access Points	<ul> <li>AP110</li> <li>AP433e/AP433i/OAP433e</li> <li>AP433is</li> <li>AP301, AP302, AP310, AP311, AP320, AP320i</li> <li>AP332e, AP332i</li> <li>AP1010i/AP1020i</li> <li>AP1010e/AP1020e</li> <li>AP1014i</li> <li>OAP180</li> <li>PSM3X</li> </ul>	<ul> <li>AP832i, AP832e</li> <li>AP822i, AP822e</li> </ul>
Controllers	<ul> <li>MC6000</li> <li>MC5000 (with or without Accelerator Module)</li> <li>MC4200 (with or without 10G Module)</li> <li>MC4100</li> <li>MC3200</li> <li>MC3000</li> <li>MC1550</li> <li>MC1500</li> <li>MC1500</li> <li>MC4200-VE</li> <li>MC1500-VE</li> <li>MC1550-VE</li> </ul>	• MC4100
System Direct Access	<ul> <li>Internet Explorer 9 and later version</li> <li>Mozilla Firefox 3.0 and Firefox 3.5+ )Vista and Win XP)</li> </ul>	
Captive Portal	<ul> <li>Internet Explorer 6, 7, 8, and 9</li> <li>Apple Safari</li> <li>Google Chrome</li> <li>Mozilla Firefox 4.x or earlier</li> <li>Mobile devices (such as Apple iPhone and blackberry</li> </ul>	

**NOTE**: A limitation of Firefox 3.0 and 3.5+ prevents the X-axis legend of dashboard graphs from being displayed.

#### **Trademarks**

Meru and Meru Networks are trademarks or registered trademarks of Meru Networks in the United States. Other company and product names may be trademarks of the respective companies with which they are associated.

#### Copyright

© 2014 Meru Networks, Inc. All rights reserved.