

NOTICE # FN-PA-AP822 Port Label Correction-111414-01

Туре	☑Product Announcement (PA)
	☐Product Support (PS)
	□End of Life (EoL)
	□Pricing (PRC)
	☐Sales & Marketing (S&M)
	☐Training (T)
Region Applicable	□APAC □EMEA □NAM ☑AII
Subject	AP822v2 port label correction notification
Field Notice Date	November 14, 2014
Effective Date	November 14, 2014
Notice Number:	FN-PA-AP822 Port Label Correction-111414-01

Notice

This field notice is provided on an "as is" basis and does not imply any kind of guarantee or warranty, including the warranty of merchantability. Your use of the information on the field notice or materials linked from the field notice is at your own risk. Meru reserves the right to change or update this field notice at any time.

Summary

Annotation of port differences between AP822v1 and AP822v2

Description of Field Notice

This notice is to provide information regarding port differences between the AP822v1 and AP822v2 access points.

- 1. There is a labeling error regarding PoE support on the AP822v2 <u>ONLY</u> G1 port has PoE support. The G2 port is labeled incorrectly.
- 2. The position of the AP822v2 G1 and G2 ports (Fig 2) are reversed from the AP822v1 position (Fig 1). (see below)





Figure 1 - AP822v1



Figure 2 - AP822v2

Affected Products

AP822v1 & AP822v2

Support for the AP822v2 access point requires installation of System Director 6.1-3.

Software is expected to be available for download on 11/17/14 on Meru's support site: http://support.merunetworks.com

Trademarks

Meru and Meru Networks are trademarks or registered trademarks of Meru Networks in the United States. Other company and product names may be trademarks of the respective companies with which they are associated.

Copyright

© 2014 Meru Networks, Inc. All rights reserved.